THERESA WYMER LA6667363

SHEET NUMBER

CE-3



SOUTH SECTION THROUGH COURTYARD SHOWING PALM TREES AROUND POOL



SOUTH SECTION THROUGH COURTYARD SHOWING TABEBUIA TREE



SOUTH ELEVATION VIEW FROM THE STREET




SOUTH SECTION THROUGH COURTYARD FACING SOUTH

EAST SECTION THROUGH COURTYARD FACING EAST



WEST SECTION THROUGH COURTYARD FACING WEST



EAST ELEVATION FACING EAST FROM FRONT DOOR

PARAMETRIKA LAND & DESIGN Gabriela Albornoz



NAEGELE RESIDENCE

COLORED ELEVATION

ISSUE DATE 03/03/2025

REVISION

Mar 2025

design **GA**

DRAWN **TY**

SCALE **N/A**

Theresa Digitally signed by Theresa Wymer Date:
2025.02.25
21:35:35 -05'00'

THERESA WYMER LA6667363

SHEET NUMBER

SITE AND LANDSCAPE PLAN

SANCUL SUAMOUNT SUAMOUNT SUAMOUNT SUAMOUNT

PARAMETRIKA LAND & DESIGN Gabriela Albornoz Theresa Wymer LA6667363



NAEGELE RESIDENCE

SHEET TITLE

COLORED ELEVATION

ISSUE DATE **03/03/2025**

REVISION

Dec 2024

GA

ΤΥ

SCALE **N/A**

Theresa Digitally signed by Theresa Wymer Date: 2025.02.25 21:35:55 -05'00'

THERESA WYMER LA6667363

SHEET NUMBER

70 Middle Road


RE: 4.A LANDSCAPE: STAFF COMMENTS

would highly recommend that this tree be removed.

4. LANDSCAPE


a. See table below:


	Total	Total Natives	Percentage Provided
Trees	0	0	N/A
Shrubs & Vines	226	126	56%
Groundcover	200	200	100%





RE: 4.A LANDSCAPE COMMENTS FROM THE OWNER:

- 1) THE ORIGINAL EXISTING FICUS BENJAMINA IS LOCATED IN THE REAR OF THE PROPERTY AND HAS GROWN INTO AND ATTACHED ITSELF TO THE "EXTERIOR SHOWER".
- 2) THE TREE PROVIDES A BROAD CANOPY, SHADE AND PRIVACY BETWEEN 70 MIDDLE ROAD AND 195 VIA MARINA.
- 3) AT SOME POINT THE TREE WILL PROBABLY DIE A NATURAL DEATH.
- 4) THEREFORE, THE OWNER PREFERS TO LET THE TREE LIVE UNTIL IT DIES NATURALLY.









9. Revisions shown hereon do not represent a "survey update" unless otherwise noted.

shown shall control the location of the improvements over scaled positions.

14. The expected horizontal accuracy of the information shown hereon is +/- 0.10'.

this survey will make this survey invalid.

relative position to the boundary.

10. All dates shown within the revisions block hereon are for interoffice filing use only and in no way affect the date of the field survey stated herein.

11 In some instances, graphic representations have been exaggerated to more clearly illustrate the relationships between physical improvements and/or lot lines. In all cases, dimensions

12. It is a violation of Rule 5J-17 of the Florida Administrative Code to alter this survey without the express prior written consent of the Surveyor. Additions and/or deletions made to the face of

13. The ownership of fences, perimeter walls and/or hedges shown hereon are not known and thus are not listed as encroachments. Fences, hedges and/or perimeter walls are shown in their

= IRON PIPE FOUND (AS NOTED)

= IRON ROD FOUND (AS NOTED)

= NAIL & DISK FOUND (AS NOTED) = MAG NAIL & DISK SET (LB #4569)

= NAIL FOUND

= PROPERTY LINE

= UTILITY POLE

= FIRE HYDRANT

= WATER METER

= WATER VALVE

= LIGHT POLE

This survey is made specifically and only for the following party for the purpose of design on the surveyed

The undersigned surveyor assumes no responsibility or liability for any other purpose or to any other party other

The South three (3') feet of the West Eighty-one (81') feet of Lot Sixty-Two (62), all of Lots Sixty-Three (63) and Sixty-Four (64) and the East ten (10') feet of Lot Seventy-Nine (79), SINGER ADDITION TO PALM BEACH, FLORIDA, according to the Plat thereof on file in the Office of the Clerk of the Circuit Court in and for Palm

adopted in Rule 5J-17, Florida Administrative Code pursuant to Section 472.027, Florida Statutes, effective September 1, 1981.

DATE OF LAST FIELD SURVEY: 6/15/2019

James S. Peden Jr. Professional Surveyor and Mapper Florida Certificate No 6122

6/15/19 SPOT ELEVATIONS, SURVEY & TIE-IN UPDATE B.M./S.W. 04-1145.4 PB279/73

BOUNDARY SURVEY FOR:

JENNIFER NAEGELE



JOB NO. 04-1145 F.B. PB362 PG 57 DFFICE M.B. DVG. ND. 04-1145-1 4/27/04 C.W. REF: 04-1145-1.DWG

70 Middle Road: 6 Variances

REVISED 3/15/24

Variances: 70 Middle Road


- 1. Section 134-893(b)(11): A variance to increase lot coverage for a <u>previously approved</u> 8 foot laundry room addition resulting in lot coverage of 34.47% in lieu of the 33.07% existing and 30% maximum allowed under the Code.
- 2. Section 134-893(b)(13): A variance to increase the cubic content ratio ("CCR") for the <u>previously approved</u> laundry room addition and <u>previously approved</u> covered terrace resulting in a Cubic Content Ratio of 8.59 in lieu of the 8.44 existing and the 3.95 maximum allowed under the Code.
- 3. Section 134-893(b)(7): A variance to reduce the side (North) yard setback for the <u>previously approved</u> laundry room addition and <u>previously approved</u> terrace railing addition (on an existing 1-story flat roof) resulting in a North side yard setback of 7.6 feet in lieu of the 12.5 foot minimum required under the Code.
- 4. Section 134-893(b)(10): A variance to increase building height of 27.4 feet in lieu of the 22 feet required under the Code for the <u>previously approved</u> 7-foot covered terrace (on the existing 1-story flat roof). Increase of overall building height for the OSHA recommended Rooftop steps resulting in 47.1 feet in lieu of the 30 feet required under the Code (13 inches higher than the existing 46 feet high flat roof).
- 5. Section 134-1728(c)(5): A variance to reduce the street (South) side yard setback for existing pool equipment and fountain equipment resulting in a street side yard setback of 15.6 feet in lieu of the 20 foot minimum required under the Code. Increase the distance between the fountain's water's edge and the fountain equipment located 54.5 feet away from the water's edge in lieu of the 25 feet maximum allowed under the Code.
- 6. Section 134-1667(a): A variance to increase the height of the <u>previously approved</u> South equipment enclosure walls in the street (South) side yard setback to 6.9 feet in height in lieu of the 6 foot maximum allowed under the Code.

- a) Please Note: The previous Attorney forgot to include the height variance required for the <u>previously approved</u> "addition of a 7-foot covered terrace on the 1962 non-original existing 1-story flat roof". To <u>avoid</u> INJURY or DEATH (and to avoid 3rd party liability) the Owner needs to INSTALL new OSHA recommended Rooftop steps to safely access the 2 flat roofs (not visible from any angle, street view or right of way)(whereby a NEW variance was added).
- b) In 2019, the owner did <u>not</u> know that the "pool equipment" would need to be relocated (whereby a NEW variance was added). The pool can <u>not</u> be installed until it is known where the pool equipment will be located due to running pipe and conduits etc.).
- c) The owner is proposing a "front yard fountain" (using the original fountain set within a half circle fountain (whereby a NEW variance is required to allow for the future fountain equipment to be enclosed within the <u>previously approved</u> South equipment enclosure); of which will also provide the required solid wall screening concealing and providing a sound barrier for pool, fountain and A/C units in the South equipment enclosure.
- d) The <u>previously approved</u> South equipment enclosure requires a "height variance" to cover and screen the pool equipment, fountain equipment and the A/C Units (whereby a NEW variance was added); of which will also provide the required solid wall screening concealing and providing a sound barrier for equipment located in the South equipment enclosure.
- e) Re: The <u>previously approved</u> "8 foot laundry room addition (91 sq. ft.) to the existing 1952 non-original structure": **The 8 foot** Laundry room addition will provide the required solid wall screening concealing and providing a sound barrier for the existing A/C equipment in the North A/C equipment enclosure.
- f) These Variances will allow the Owner to finish 3 major areas to include:
 - 1) Family Room Rebuild (North side of House)
 - 2) Laundry Room Rebuild (North west corner of house)
 - 3) Pool installation

Please note: 2024 Variances: The 6 current Variances reference 3 specific areas with 3 New Variances.


The 3 specific areas show the number of Variances required. Please review the "Variance Synopsis" detailed below:


- 1 a) The Owner needs to INSTALL new OSHA recommended flush Roof steps to safely access the 2 flat roofs. The OSHA recommended steps are a necessity and not a frivolity. The OSHA recommended steps are a safety measure so the owner's staff and maintenance crew do not suffer catastrophic FALLS, INJURY or DEATH while performing various maintenance and/ or roof repairs. The approval of the OSHA recommended steps will not confer any special privilege nor would they be detrimental to the public welfare. However, not installing the OSHA recommended steps could result in injury or death; of which the owner is seeking to avoid 3rd party liability. (not visible from any angle, any street view or any right of way) (whereby a NEW variance was added).
- 1b) Construction of a <u>previously approved</u> **7 foot covered terrace** on existing 1969 non-original 1-story flat roof. **(3 Variances: Variance # 2,3,4)**
- 2) Construction of a <u>previously approved</u> **8-foot laundry room addition** (91 sq. ft.) to the existing 1952 non-original structure.
- (3 Variances: Variance # 1,2,3)
- 3) Construction of a <u>previously approved</u> **South equipment enclosure** to enclose the pool, future fountain and A/C equipment. Installation of fountain equipment located 54.5 feet away from the water's edge.
- (2 Variances: Variance # 5,6)



NOTES FROM THE OWNER:

- THE OSHA APPROVED STEPS ARE A SAFETY MEASURE SO THE OWNERS STAFF AND MAINTENANCE CREW DO NOT SUFFER CATASTROPHIC FALLS FROM THE ROOF WHILE PERFORMING VARIOUS MAINTENANCE AND/ OR ROOF REPAIRS.
- THE OSHA APPROVED STEPS ARE A NECESSITY.
- THE OWNER'S FLAT ROOFS REQUIRE RE-PAINTING AND WATERPROOFING SEMI-ANNUALLY.
- 4) THE OWNER'S 3 CHIMNEYS FREQUENTLY REQUIRE CLEANIN AND MAINTENANCE DUE TO EXCESSIVE LEAVES AND DEBRIS WHICH OFTEN ACCUMULATE ON THE FLAT ROOFS DURING HIGHWINDS, STORMS AND HURRICANES.
- 5) THE OWNER'S HAND MADE CLAY ROOF TILES OFTEN CRACK BREAK AND DETACH DURING HIGH WINDS, STORMS AND HURRICANES; WHICH REQUIRE IMMEDIATE REPLACEMENT TO AVOID FUTURE CODE VIOLATIONS.
- 6) THE OSHA APPROVED STEPS PROVIDE A SAFER AND MORE EFFICIENT ACCESS BETWEEN THE TWO FLAT ROOFS; REDUCING THE NEED FOR LADDERS AND OTHER POTENTIALLY HAZARDOUS ACCESS METHODS TO TRANSITION BETWEEN THE TWO FLAT ROOF FOR CHIMNEY AND ROOF ACCESS.
- 7) THE OSHA APPROVED STEPS ARE NOT VISIBLE FROM ANY RIGHT OF WAY OR STREET VIEWS.
- 8) APPROVAL OF THE OSHA APPROVED STEPS WILL NOT CONFER ANY SPECIAL PRIVILEGE NOR WOULD THEY BE DETRIMENTAL TO THE PUBLIC WELFARE. HOWEVER, NOT INSTALLING THE OSHA APPROVED STEPS COULD RESULT IN INJURY OR DEATH; OF WHICH THE OWNER IS SEEKING TO AVOID 3RD PARTY LIABILITY.





ROOF STRINGER STEPS NOT VISIBLE FROM STREET OR RIGHT OF WAY



70 Middle Road

MIDDLE RD - EAST VIEW





MIDDLE RD - NORTH VIEW



MIDDLE RD/VIA MARINA CORNER




VIA MARINA - SOUTH VIEW



PHOTOS SHOWING ROOF STEPS NOT VISIBLE FROM STREET OR RIGHT OF WAY





EXISTING NORTH ELEVATION

SCALE: 37"=1'-0"




SCALE: 37"=1'-0"





EXISTING WEST ELEVATION






PREVIOUSLY APPROVED WEST ELEVATION


SCALE: 32"=1'-0"









- 2. Section 134-893(b)(13): A variance to increase the cubic content ratio ("CCR") for the <u>previously approved</u> laundry room addition and previously approved covered terrace resulting in a Cubic Content Ratio of 8.59 in lieu of the 8.44 existing and the 3.95 maximum allowed under the Code.
- 3. Section 134-893(b)(7): A variance to reduce the side (North) yard setback for the <u>previously approved</u> laundry room addition and <u>previously approved</u> terrace railing addition (on an existing 1-story flat roof) resulting in a North side yard setback of 7.6 feet in lieu of the 12.5 foot minimum required under the Code.
- 4. Section 134-893(b)(10): A variance to increase building height of 27.4 feet in lieu of the 22 feet required under the Code for the <u>previously approved</u> 7-foot covered terrace (on the existing 1-story flat roof). Increase of overall building height for the OSHA recommended Rooftop steps resulting in 47.1 feet in lieu of the 30 feet required under the Code (13 inches higher than the existing 46 feet high flat roof).




- 1. Section 134-893(b)(11): A variance to increase lot coverage for <u>previously approved</u> 8 foot laundry room addition resulting in lot coverage of 34.47% in lieu of the 33.07% existing and 30% maximum allowed under the Code.
- 2. Section 134-893(b)(13): A variance to increase the cubic content ratio ("CCR") for the <u>previously approved</u> laundry room addition and covered terrace resulting in a Cubic Content Ratio of 8.59 in lieu of the 8.44 existing and the 3.95 maximum allowed under the Code.
- 3. Section 134-893(b)(7): A variance to reduce the side (North) yard setback for the <u>previously approved</u> laundry room addition and previously approved terrace railing addition (on an existing 1-story flat roof) resulting in a North side yard setback of 7.6 feet in lieu of the 12.5 foot minimum required under the Code.





5. Section 134-1728(c)(5): A variance to reduce the street (South) side yard setback of <u>previously approved</u> South equipment enclosure for existing pool equipment and fountain equipment resulting in a street side yard setback of 15.6 feet in lieu of the 20 foot minimum required under the Code. Increase the distance between the fountain's water's edge and the fountain equipment located 54.5 feet away from the water's edge in lieu of the 25 feet maximum allowed under the Code.



6. Section 134-1667(a): A variance to increase the height of the <u>previously approved</u> South equipment enclosure walls in the street (South) side yard setback to 6.9 feet in height in lieu of the 6 foot maximum allowed under the Code.

- 70 Middle Road: Section 134-201 Findings prior to authorization.
- 1. The special conditions and circumstances related to the subject property is that this is a Historic Landmarked house in the R-B Zoning District that is currently non-conforming to the current Code.
- 2. The special conditions and circumstances are not the result of the applicant as the house was built in 1924 (with later additions in 1952 and 1969). The non-conforming aspects of the house were in existence at the time of acquisition by the applicant.
- 3. The hardship, which runs with the land, is that the house is a Town of Palm Beach Historic Landmark house (built in 1924) which is non-conforming in several aspects to the current Code as zoning has changed since the house was originally constructed 100 years ago.
- 4. The current location and configuration of the Landmark house limits the applicant's ability to make changes without the necessity for variances. Renovations to a Landmark house require a delicate approach in making changes to improve the livability for the year 2024.
- 5. The <u>previously approved</u> 8-foot laundry room addition (extended from the 1952 non-original structure) is relatively small and will allow for greater livability of the property to conform to current standards. The variances requested are the minimum necessary to make reasonable use of the land. The <u>previously approved</u> 8-foot (91 square foot) laundry room addition in the North West corner of the house will be no farther into the setback than the rest of the house currently is. The <u>previously approved</u> 8-foot laundry room addition will be no closer to the North property line than other portions of the house currently are (to also include providing the required solid wall screening concealing and providing a sound barrier for the existing North A/C equipment).

- 70 Middle Road: Section 134-201 Findings prior to authorization.
- 6. The <u>previously approved</u> 7-foot covered terrace on the existing 1-story flat roof of the 1969 non-original addition will not be any closer to the North property line than the flat roof currently is; nor would it be any higher than the original clay barrel tile roof currently is. The <u>previously approved</u> 7-foot covered terrace is a significant improvement to the 1969 non-original 1-story addition creating cohesion and unification of the North exterior elevation of the Landmarked house.
- 7. The relocation of the pool equipment and future fountain equipment are necessary for the pool, spa and fountain and will be enclosed within the previously approved South equipment enclosure. The pool equipment and fountain equipment will be lower in height and farther from the property line than the existing equipment is currently situated (concealed within the South equipment enclosure providing the required solid wall screening and sound barriers).
- 8. The OSHA recommended steps are a safety measure so the owner's staff and maintenance crew do not suffer catastrophic FALLS, INJURY or DEATH while performing various maintenance and/ or roof repairs. The owner's flat roofs require re-painting and waterproofing semi-annually. The owner's 3 chimneys frequently require cleaning and maintenance due to excessive leaves and debris which often accumulate on the flat roofs during high winds, storms and hurricanes. The owner's hand made clay roof tiles often crack, break and detach during high winds, storms and hurricanes; which require immediate replacement to avoid future code violations. The OSHA recommended steps provide a safer and more efficient access between the two flat roofs; reducing the need for ladders and other potentially hazardous access methods to transition between the two flat roofs for chimney and roof access. The OSHA recommended steps are not visible from any right of way or street views. The OSHA recommended steps are a necessity and not a frivolity. The approval of the OSHA recommended steps will not confer any special privilege nor would they be detrimental to the public welfare. However, not installing the OSHA recommended steps could result in injury or death; of which the owner is seeking to avoid 3rd party liability.
- 9. The granting of these variances will not be injurious to the area involved or detrimental to the public welfare. Granting of the variances requested will not confer any special privilege that is denied to the neighboring properties.

