NORTHWORKS Hunt Residence ARC -24-0106 ZON-24-0063 260 Colonial Ln, Palm Beach, FL 33480



NORTH ELEVATION





COMMENT 1: REGULARIZE ROOF SLOP

- COMMENT 2: REDUCE DOOR TO 42" W
- COMMENT 3: REDUCE ENTRY GATE TO
- COMMENT 4: REDUCE THE DRIVEWAY

• COMMENT 5: STUDY WINDOW SCALE AND PLACEMENTS ON NORTH FACADE

PES	
VIDE	
DONE DOOR	
EAND	

STUDIED AND FULLY INCORPORATED ----

FULLY INCORPORATED

FULLY INCORPORATED

FULLY INCORPORATED

STUDIED


SHEET A1.02
SHEET A2.00 & A5.00
SHEET A5.01
SHEET A0.07
SHEET A2.00



RESEARCH AND PRECEDENTS

" BY THE EARLY 19TH CENTURY WHEN HIP ROOFS HAD LARGELY REPLACED GABLE ENDED ROOFS, THERE WAS MUCH LESS NEED FOR THE END BUTTRESSING OF A CHIMNEY... THESE CHANGES MEANT THAT THERE WAS ALSO AN ATTENDANT LOWERING OF THE PITCH OF THE ROOFS FROM A 10/12 TO A 6/12 PITCH OR EVEN LESS."

- "UNDERSTANDING THE BERMUDA ROOF" BY THE BERMUDA NATIONAL TRUST












RESEARCH AND PRECEDENTS

" BY THE EARLY 19TH CENTURY WHEN HIP ROOFS HAD LARGELY REPLACED GABLE ENDED ROOFS, THERE WAS MUCH LESS NEED FOR THE END BUTTRESSING OF A CHIMNEY... THESE CHANGES MEANT THAT THERE WAS ALSO AN ATTENDANT LOWERING OF THE PITCH OF THE ROOFS FROM A 10/12 TO A 6/12 PITCH OR EVEN LESS."

- "UNDERSTANDING THE BERMUDA ROOF" BY THE BERMUDA NATIONAL TRUST










PREVIOUSLY PROPOSED ROOF PLAN




COMMENT 1 - REGULARIZE ROOF SLOPES

RESPONSE: WE HAVE DONE A SERIES OF ROOF STUDIES AND BELIEVE THAT A 10/12 SLOPE AT THE ENTRY WITH A 5/12 SLOPE FOR THE REMAINDER OF THE ROOF IS THE BEST VERSION

- PROPERTY LINE

- PROPERTY LINE

NEW PROPOSED ROOF PLAN




COMMENT 1 - REGULARIZE ROOF SLOPES

- PROPERTY LINE








COMMENTS 2 AND 3- REDUCE DOOR TO 42" AND REDUCE ENTRY GATE TO ONE DOOR

RESPONSE: DOOR HAS BEEN REDUCED TO 42" AND GATE HAS BEEN REDUCED TO ONE DOOR






PREVIOUSLY PROPOSED DRIVEWAY



COMMENT 4- REDUCE DRIVEWAY SIZE

RESPONSE: THE DRIVEWAY HAS BEEN REDUCED BY 1 FOOT ON EVERY SIDE

NEW PROPOSED DRIVEWAY



PROPERTY LINE







RESPONSE: WE HAVE STUDIED THE DIVISIONS ON THE WINDOWS AND MADE SURE THEY ARE THE SAME SCALE. WE ALSO STUDIED THE PLACEMENT OF THE WINDOWS BUT BELIEVE THAT THE PREVIOUSLY PROPOSED LOCATION WORKS BEST.

COMMENT 5- STUDY WINDOW SCALE AND PLACEMENTS ON NORTH FACADE

NORTHWORKS

NORTH ELEVATION






APPENDIX





ROOF STUDIES - 7:12S











7:12S WITH 12:12 ENTRY








7:12 WITH 10:12 STEPPED BUTTERY ENTRY



7:12 WITH 10:12 STEPPED BUTTERY ENTRY



ROOF STUDIES - 7:12S


7/12 STEPPED BUTTERY ENTRY, OTHERS 7/12



ENTRY 12/12, OTHERS 7/12




ALL 7/12






ROOF STUDIES - 6:12S











6:12S WITH 11.5:12 ENTRY




6:12S WITH 11.5:12 ENTRY



6:12S WITH 10:12 STEPPED BUTTERY ENTRY



6:12S WITH 10:12 STEPPED BUTTERY ENTRY



ROOF STUDIES - 6:12S



ALL 6:12



6:12 WITH 11.5:12 ENTRY




6:12 WITH 10:12 STEPPED BUTTERY ENTRY

5:12S WITH 10:12 BUTTERY ENTRY




5:12S WITH 10/12 STEPPED BUTTERY ENTRY




5:12S WITH 10:12 ELEVATED STEPPED BUTTERY ENTRY



5:12S WITH 10:12 ELEVATED STEPPED BUTTERY ENTRY





ROOF STUDIES - 5:12S



5:12S WITH 10:12 STEPPED BUTTERY ENTRY



5:12S WITH 10:12 ELEVATED STEPPED BUTTERY ENTRY



