

**PALM BEACH COUNTY
LAKE WORTH INLET SAND TRANSFER PLANT
ANTICIPATED FY2019 REPAIR COSTS AS OF 4/3/19**

Repair Item	Manufacturer	Quote¹	Quote Date
replace suction hose	H.S. White	\$ 9,783.00	1/31/19 re-quote. Hose ordered 2/15/19.
replace jet line	H.S. White	6,363.00	2/27/19
overhaul hydraulic crane ²	Techcrane International, Inc.	49,198.58	2/27/19
reducers and flanges	McKinsey Steel	3,912.00	1/21/19
jet pump	Electric Motors of PB	4,651.00	1/4/19
jet pump motor connectors (flanges)	Miller/Motion Industries, Inc.	209.32	1/17/19
planetary drive gear	Techcrane International, Inc.	5,404.28	4/2/19
Total Anticipated FY19 Repair Costs		\$ 79,521.18	

¹Anticipated costs are based on current quotes or estimates and are subject to changing market conditions.

²Quote does not include new cylinders. New cylinders were installed in 2018.