Town of Palm Beach Marina

Project No: 12717.201

Late revision date: April 29, 2021

Green Space Comparison

	Convert To Green Space from Hardscape		Convert to Hardscape from Greenscape		
Location & Net					
Change (sf)	Area (sf)	Description	Area (sf)	Description	
Palm Way and	S-1				
	333.6	5 Palm Way Lake Trail	-83.2	Palm Way Disconnects	
			-180.3	Palm Way Path from Dock to Lake Trail	
		4	-115.0	S-1 Switch boxes in park	
-44.9	2 333.6	5	-378.5		
Brazilian					
	120.7	7 Brazilian garbage	-198.4	Brazilian Path from Dock to Lake Trail	
	11.3	Brazilian Pump Out	C	Brazilian Stairs (already hardscape) 56.8 sf	
	34.1	L Brazilian transformers	C	Brazilian Ramp from parking lot to Lake Trail (already hardscape)	
	16.4	1 Brazilian transformers	457	Brazilian parking lot area (positive as it converts hardscape to greenspace)	
	8.1	l catv	268.3	Brazilian parking lot area (positive as it converts hardscape to greenspace)	
	169.8	Brazilian Path from Dock to Lake Trail	72.7	Brazilian parking lot area (positive as it converts hardscape to greenspace)	
		Brazilian circles for trees (already greenspace	-16.5	Brazilian A/C pads	
			-48.6	Brazilian Disconnects	
			-112.3	Brazilian transformers	
			-21.4	Twin electrical junction boxes on south side of Brazilian parking lot	
782.	6 360.4	1	422.2		
Australian					
	261.9	Australian Path from Dock to Lake Trail	-190.4	Australian Path from Dock to Lake Trail	
	42.1	L Australian lift station	-455.4	Australian grass area in center west of parking lot	
	11	l Australian Sewer	-100	Australian grass area in northwest corner of parking lot	
	125.6	5 Australian electrical gear	-161.2	Australian transformers	
		-	-27.4	Australian disconnects	
			-26.3	Australian lift station	
			-5.5	Australian A/C	
-525.	6 440.6	5	-966.2		
Peruvian	202.5	B Peruvian Path from Dock to Lake Trail	160 7	Peruvian Path from Dock to Lake Trail	
				Peruvian transformers	
		3 Peruvian Transformers		Peruvian transformers Peruvian Lift Station	
		5 Peruvian sewer			
	1.5	5 CATV		Peruvian Disconnects	
	4 000			Peruvian southwest of D-6 Elec building	
-8.	1 298.6		-306.7		

Bulkhead			
	OO C Dellahaa I	month of Dalus 144	
		north of Palm Way	
		Palm Way to Brazilian	
	139.5 Bulkhead		
		D-6 to Australian	
		Australian to D7	
000	148.3 Bulkhead	D-7 to Peru	
958	958		
Net Excluding Paths			
1162 sf			Lake Trail length
			505.1 Palm Way to D-6
			460 D-6 to D-7
			193 D-7 to Peruvian
			1158.1 ft
Fairfax Sammons Pa	ths through Park		
Fairfax Sammons Pa	ths through Park		-1457.1 FS Brazilian Path
Fairfax Sammons Pa	ths through Park		-782.3 FS Chilean Path
Fairfax Sammons Pa	ths through Park		-782.3 FS Chilean Path -538.6 FS Peruvian Path
Fairfax Sammons Pa	ths through Park		-782.3 FS Chilean Path
			-782.3 FS Chilean Path -538.6 FS Peruvian Path
Revised Paths throug			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path
			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot
			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path
			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path
Revised Paths throug			-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths throug	gh Park	mons	-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths through Net Including Paths	g h Park Fairfax Sam	mons	-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths throug	gh Park	mons	-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths through Net Including Paths	gh Park Fairfax Sam Option 2		-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths through Net Including Paths -1616 sf -1291 sf	gh Park Fairfax Sam Option 2	mons with 4' path	-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lot -690.4 Australian Path -653.5 Peruvian Path
Revised Paths through Net Including Paths -1616 sf -1291 sf -1149 sf	Fairfax Sam Option 2 Fairfax Sam Option 2 with	mons with 4' path	-782.3 FS Chilean Path -538.6 FS Peruvian Path -2778 FS Path -1108.8 Brazilian path along parking lor -690.4 Australian Path -653.5 Peruvian Path -2453 Option 2

4' v	vide path -1201 -678 26 -432 -2311	60 sf	50 sf each sitting area (200 sf) - 105 sf for S Lake Drive Parallel Section
4'			
	-906		
	-556	556	564 Revised Australian with crossing on north side of
	-541		and a substitution of the
	-2003		