Complex structural repairs, including deteriorated steel beams and columns, are critical and urgently needed. These images highlight the severity of the damage, underscoring the necessity for completion by January 2025
















New replaced beam on the Left. Old deteriorated beam on the right.  $\label{eq:left}$ 





